


# DRILL PRESS DIAGRAM – MODEL : DP1000W20



## SPARE PART LIST (DP1000W20)

ITEM	CODE	ITEM DESCRIPTION	SPECIFICATION	Q'TY
1	DP20B01	BASE		1
2		COLUMN FLANGE		1
3		SPRING WASHER	10	4
4		OUTSIDE HEX. BOLT	M10x25	4
5		RACK		1
6		COLUMN		1
7		CROSS RECESS PAN HD SCREW	M6x12	1
8		COLLAR RACK		1
9	DP162122N/200910	HANDLE TIP (I5)	} IN ONE SET	3
10	DP20B12	HANDLE (I5)		3
11		HANDLE SEAT		1
12		DIAL SCALE		1
13		ROLL PIN	5x16	1
14		LOCKING HANDLE KNOB	M8X18	1
15		GEAR SHAFT		1
16		ROLL PIN	5X20	1
17		ROLL PIN	6X18	2
18		LOCKING HANDLE KNOB	M10X25	2
19		HANDLE BELT TENSION		1
20		CIRCLIP FOR BEARING	15	1
21		CIRCLIP FOR BEARING	16	1
22		SLIP SHAFT		1
23		ADJUSTING SHAFT		1
24		FLAT WASHER	12	4
25		OUTSIDE HEX. BOLT	M8x25	4
26		FLAT WASHER	8	8
27		MOTOR CONNECTION PLATE		1
28		NUT	M12	2
29		HEX. SOC SET SCREW	M6x10	3
30	DP20B36	MOTOR PULLEY		1
31	DP20M	MOTOR (K4)		1
32		SPRING WASHER	8	4
33		NUT	M8	5
34		CAM ASSEMBLY		1
35		HEX. SOC SET SCREW	M8x10	3
36		DAMPING WASHER		4
37	DP20B46	PULLEY COVER		1
38		FLAT WASHER	6	4
39		CROSS RECESS PAN HD SCREW	M6x10	4
40		ECCENTRIC SHAFT		1
41		MIDDLE PULLEY		1
42		BEARING	6202	2
43		CIRCLIP FOR HOLE	35	1
44	DP2044O565E	V-BELT (C71)	O-565E	1
45		PULLEY COVER KNOB	M4	1
46		BIG FLAT WASHER	4	1
47		CROSS RECESSED PAN HEAD SCREW	M4x10	1
48	DP2044O710	V-BELT (C71)	O-710	1
49	DP2049	SPINDLE PULLEY (C71)		1
50		CIRCLIP FOR HOLE	40	2
51	DP2051	KEYWAY SPINDLE (C71)		1
52		BEARING	6005	3
53		TOOTH LOCK WASHER	5	1
54		GROUNDING PARTS	5	1
55		CROSS RECESS HEAD SCREW	M5x6	1
56	DP2056	SWITCH (C71)		1

### SPARE PART LIST (DP1000W20)

ITEM	CODE	ITEM DESCRIPTION	SPECIFICATION	Q'TY
57		CROSS RECESS HEAD SCREW	M5x10	2
58		CABLE FLANGE	M12	2
59		PLUG WITH CABLE		1
60		A WORD HEAD SCREW	M8X25	1
61	DP206162	SPRING (C71)	} IN ONE SET	1
62	DP206162	SPRING COVER (C71)		1
	DP20B6162	COIL SPRING & SPRING COVER		
63		THIN NUT	M12	2
64		HOUSING		1
65		CRANK		1
66	DP20B29	OUTSIDE HEX BOLT	M16x12	1
67		CIRCLIP FOR BEARING	14	1
68		WORM		1
69		WORM GEAR		1
70		LOCKING HANDLE	M12X45	1
71	DP20B08	TABLE BRACKET/TABLE SUPPORT (C71)		1
72		WORM PIN		1
73		LOCKING HANDLE	M10X32	1
74		SPRING WASHER	16	1
75		OUTSIDE HEX BOLT	M16x30	1
76		TABLE ARM		1
77		WORKING TABLE		1
	DP20787980818384	CIRCLIP,BEARING,SPINDLE SOCKET,MAIN SPINDLE,BEARING,WASHER		
78		CIRCLIP FOR BEARING	12	1
79		BEARING	6203	1
80	DP20B80	SPINDLE SOCKET (C71)	} IN ONE SET	1
81	DP20B81	MAIN SPINDLE (C71)		1
82		THICK BRAKE IRON		1
83		BEARING	6005	1
84		WASHER		1
85	DP2085/DP20B85	TAPER SPINDLE (C71)		1
86	DP2086K/DP20B86K	CHUCK C/W KEY (C71)		1
87		HEXAGON BAR WRENCH	4	1
88		BEARING RING		1
	DP20BC	Capacitor / Condensor (C80)		
	DP20C	Capacitor/ Condensor (C71)		
	DP20BM	Motor (O14)		
	DP20M	Motor (K4)		
	DP20B46	PULLY COVER		